

RETROFIT

August 2012

PRODUCTS AFFECTED:

Wheel aligner with electronic - tilt camera system accessory hinges produced between 2009 and 2010 made by Snap-on Equipment and distributed under the John Bean and Hofmann brands.

PART NAME & DESCRIPTION:

Electronic – Tilt Camera System

This accessory allows a fixed beam aligner to tilt thereby changing the view angle of the camera system.

Electronic – Tilt Camera System



PART NUMBER:

EAK0289J64A

EAK0289J64B

EAK0289J79A

HAZARD:

The weld that joins the two halves of the tilt camera system hinge plates may fracture and break causing the beam to suddenly fall from an elevated position. This may cause death, serious personal injury or property damage.

QUESTIONS:

If you have questions on this advisory or need assistance contact: [Customer Service at \(800\) 225-5786](tel:8002255786)

ACTIONS:

Do not stand, or place personal property, under or near the camera beam until the retention device has been installed.

Snap-on Equipment is voluntarily supplying and installing a retention device that prevents the camera beam from falling in the event a weld failure occurs.

If your aligner is equipped with a tilt camera system and has been identified by this Product Safety Retrofit as being manufactured between 2009 and 2010, Snap-on Equipment will be contacting you to schedule a retention device installation.

The build date of the aligner can be determined by the serial number located on the back of the unit. If the serial number has a "C" or a "D" in the fourth digit, and has an Electronic Tilt System, the unit is affected by this advisory.

If you have questions or would like to confirm your tilt camera system manufacture date and therefore the applicability of this advisory, call customer service at (800) 225-5786.

QUESTIONS:

If you have questions on this advisory or need assistance contact: [Customer Service at \(800\) 225-5786](tel:8002255786)