

Part 70 Compliance Certification Report due April 1st

Your facility is currently operating under a Part 70 Operating Permit issued by the Air and Radiation Administration (ARA). This permit requires an annual Compliance Certification due by April 1 each year. To complete the compliance certification, both an ARA form and a federal Compliance Certification form are to be used. The ARA form is to be used for certifying plant-wide conditions (Section III of your Part 70 Permit) and the federal form is to be used for certifying plant-specific conditions (Section IV of your Part 70 Permit).

Regarding the federal form, please note that sections A and B of the certification form are only required to be completed once; however, sections C and D must be completed for each permit condition of each emission unit. Deviations from permit conditions must be reported on form E. Please make as many copies of form C, D, and E as necessary.

The federal form and instructions are located at:

<https://www.epa.gov/title-v-operating-permits/epa-issued-operating-permits>

The ARA form for Section III is located at:

<https://mde.maryland.gov/programs/Air/AirQualityCompliance/Pages/index.aspx>

Please ensure that your certification is received by ARA on or before April 1st. Completed forms should be sent electronically to: **mdeair.ACOMP@maryland.gov**

Failure to meet this deadline is a violation of your Part 70 Permit.

A copy of your annual compliance certification must also be sent electronically to the Environmental Protection Agency, Region 3 at the following address: **R3_APD_Permits@epa.gov**

If you have any questions, please call your ARA contact at 410-537-3231.

Sincerely,



Pars Ramnarain, Chief
Process Compliance Division
Air and Radiation Administration